

Basic Machinist (BM31) Certificate eMap

This eMap, along with regular meetings with your program advisor and using DegreeWorks, will help you remain on track to finish your program as quickly as possible and graduate from Georgia Northwestern Technical College. This eMap is intended to be used when beginning the program in Fall semester. Starting the program in Spring or Summer semesters may alter the suggested courses or course availability. This pathway is based on the 2026-2027 academic year.



1 st set of suggested courses			
Course		Hours	Completed
MATH 1012	Foundations of Mathematics	3	☐
MCHT 1011	Introduction to Machine Tool	4	☐
MCHT 1012	Print Reading for Machine Tool	3	☐

Total Credit Hours: 10 Minimum Credit Hours Required to Complete Certificate

Basic Machinist Certificate Planning Notes:

- Classes for this Certificate are offered at the Floyd County Campus and the Whitfield Murray Campus. Schedules at each campus may vary.
- Floyd County Campus program advisor: Bart Jenkins, bjenkins@gntc.edu
- Whitfield Murray Campus program advisor: Cory Horton, chorton@gntc.edu

Additional information for the Basic Machinist Certificate and program requirements can be found at [GNTC 2026-2027 Catalog](#).